



BS-9

SIGN:

Warning Dangerous
Undertow and Strong Current
in this Area

COMMENT:

Sign rusted and difficult
to read.

RECOMMENDATION:

Repaint sign. Possibly need
to reposition to prevent future
rusting.



BS-10

SIGN:

No Trespassing

COMMENT:

Poor spacing of message.
No company/owner
information.

RECOMMENDATION:

Replace with standard No
Trespassing sign with small
company contact information.